## **Assessment Record**



Program:	Physical Plant	Assessment period:	2019-2020

## **Program or Department Mission:**

The primary purpose of Physical Plant Operations is to provide an attractive, clean, and safe physical environment conducive to achieving the stated purposes of the college.

Service Unit Outcomes & Assessment Plan					
Intended Outcomes	Means of Assessment	Criteria for Success	Summary & Analysis of Assessment Evidence	Use of Results	
A plan for the upkeep of college property, which addresses	Review maintenance records of routine and preventive actions.	Complaints from faculty, staff, and students will be kept to a minimum on maintenance related issues.	An increase in roof leaks and repairs to LWH indicate the need for a new roof.	Replacement of roof has been approved and work should begin soon.	
routine, preventive, and deferred maintenance is developed and			An increasing number of roof leaks on the George Layton building indicate the need for a new roof.	Roof installation is complete.	
implemented.			Some repairs have been made to decks with aging issues on FSC decks.	Plans for additional repairs are being made as needed to the FSC decks.	
			Engineers have prescribed repairs to correct improperly installed precast soffits on GSB discovered earlier on the Shelby/Hoover campus.	Repairs are complete.	

			Ruby Carson elevator has become mechanically problematic.	Elevator is currently being renovated.
			H. Y. Carson cooling tower. Due to age and deterioration the tower needs to be replaced.	The cooling tower has been replaced and is operational.
			HVAC was lost in the culinary classroom in FSC.	A new air handler has been installed and HVAC has been restored.
The unit will ensure that safe, attractive and accessible facilities,	Inspection of facilities and complaints from the college community	Complaints from faculty, staff, and students are kept to a minimum, while receiving compliments from	Aesthetic and physical repair projects were identified this past year.	Repainting of classrooms, hallways, stairwells, offices and other areas are ongoing.
adequate and appropriate for the operation of the college, are provided.		visitors and students	Windows in Manufacturing building showing signs of deterioration and problems with leaks. Windows need to be replaced.	Windows are currently being replaced on remaining areas of the top floor.
			Exterior renovations at Allen Library have been identified.	Exterior renovations have been completed to include a new portoco, entrance, retaining wall, and stamped concrete walk way.
The unit will effectively respond to emergency and short-notice maintenance issues that threaten interruption of college functions.	All emergencies and short- notice maintenance issues are reported to the maintenance department.	No classes or college functions cancelled due to emergency or short-notice maintenance issues	Emergency and short-notice maintenance issues have been successfully responded to and resolved.	No classes or functions have been canceled due to maintenance issues this year.

The unit will assist other areas in renovation planning, budgeting and implementation to accommodate changing needs.	The Maintenance Director meets with cost center heads, contractors, appropriate dean, and budget planners to accommodate the need of keeping all areas up to date in technology and aesthetics	The maintenance department will complete approved projects in a timely manner.	A need for the development of an additional welding lab was identified.  It was determined that a wall was needed to separate welding from the electronics in the ICademy bldg	The Welding Center is nearing completion and should be ready for use soon.  Wall has been completed and HVAC was re-ducted to accommodate for the wall.
The college will achieve compliance with all local, state, and federal safety/health regulations as required.	Inspectors from the state department of labor, fire inspectors, and other local inspectors notify the maintenance department of any deficiencies.	The college will have no violations from authorities having jurisdiction over health/safety regulations	Elevator, boiler, fire, and grease trap inspectors notify the maintenance department of any deficiencies.	All deficiencies reported after inspections were corrected.
The college will make efforts to use energy resources in the most effective manner.	The maintenance department is vigilant in monitoring energy uses	Reducing total energy costs or maintaining them at a level of no increase	Plans are being formulated for future updating of HVAC controls to ensure comfort and energy saving.	The 1 <sup>st</sup> and 2 <sup>nd</sup> floor HVAC controls in HSB have been completed. The 3 <sup>rd</sup> floor has been approved and will begin soon.
			Health Science bldg. 4 <sup>th</sup> floor controls. Controls are outdated and replacement parts are no longer available.	Plans to replace controls will be scheduled for the upcoming year.
			With the current lighting being outdated and the energy efficiency of LED lighting it is our plan to begin converting to LED's.	LED lighting has been installed in AL, LWH, BDH, and GLB. Current plans are to continue throughout the remaining bldgs. at the Carson Campus.
Plan submission date: 9/16/20		Submitted by: Perry L. Harris		